

Evan's Inspection Service, Inc.  
 15253 Hollywood Road  
 Monticello, Iowa 52310  
 (319) 481-9059

Bulk Sample Inventory Of Suspect Asbestos Containing Materials

City of Mystic  
 106 South 3<sup>rd</sup> Street  
 Mystic, IA

Sample #	Room or Area	Material	Description	NF* or F	Homo or Het	Location	UOM or Unit	%ACM
01	Debris field	Tar paper	Black thick	F	Homo	30 x 40 – no basement	M1	NAD
02	Debris field	Tar	Black	F	Homo	Approximately 50 yards	M2	10% Chrysotile
03	Debris field	Original plaster	Gray sandy	F	Homo	Approximately 50 yards	M3	NAD
04	Debris field	Original plaster	Gray sandy	F	Homo	Approximately 50 yards	M4	NAD
05	Debris field	Original plaster	Gray sandy	F	Homo	Approximately 50 yards	M5	NAD
06	Debris field	Insulation	Gray cellulose	F	Homo	Approximately 50 yards	M6	NAD
07	Debris field	Tar	Black	F	Homo	Approximately 50 yards	M7	NAD
08	Debris field	Tar paper	Black med thick	NF	Homo	Approximately 50 yards	M8	NAD
09	Debris field	Shingle	Tan red	F	Homo	Approximately 50 yards	M9	NAD
<b>Wooden Outbuilding</b>								
10	Wooden shed	Shingle	Green asphalt	F	Homo	Approximately 500 sq ft base	M10	NAD
11	Wooden shed	Shingle	Green asphalt	F	Homo	Approximately 500 sq ft layer 2	M11	NAD
12	Wooden shed	Shingle	White asphalt	F	Homo	Approximately 500 sq ft top layer	M12	NAD
13	Wooden shed	Tar	Black	F	Homo	Approximately 500 sq ft patches	M13	10% Chrysotile
14	Wooden shed	Tar	Gray white specks	F	Homo	Approximately 500 sq ft patches	M14	10% Chrysotile

\*NAD=No Asbestos Detected      Bold text mean materials contain Asbestos.

- Notes:
1. House 90-95% burned.
  2. Only one outbuilding had suspicious materials on roof.
  3. Any demolition needs to be performed by a permitted asbestos contractor. Estimates are approximate. Contractor to verify. Not for third party use.